


A course in electrical engineering Volume 2



Filesize: 8.46 MB

Reviews

This created book is wonderful. It is amongst the most amazing book i have got go through. I am just effortlessly will get a enjoyment of looking at a created publication.

(Prof. Jasper Murazik PhD)

A COURSE IN ELECTRICAL ENGINEERING VOLUME 2

DOWNLOAD



To save **A course in electrical engineering Volume 2** PDF, remember to click the button listed below and save the document or have access to additional information which might be in conjunction with A COURSE IN ELECTRICAL ENGINEERING VOLUME 2 book.

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 140 pages. Dimensions: 9.7in. x 7.4in. x 0.3in. This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1922 Excerpt: . . . the secondary and primary resistances, respectively, as a one-to-one ratio of rotor to stator turns is assumed. Line PG is then drawn. At any load current I_2 (P_E) is the secondary current, being equal to $I_1 - I_0$ vectorially. EA is the energy component of the current I_1 , and therefore the total power input per phase, $P_i = E_a I_1 \cos \phi$. The core and friction losses $P_c = B A X V$ per phase. The primary copper loss $I_1^2 R_1$ BC X V per phase. The secondary copper loss $I_2^2 R_2$ CD X V per phase. The output $P = E_a I_2 \cos \phi$ per phase. Draw PG parallel to PG and tangent to the circle at E. Break-down torque TB CE (to scale). The above diagram is drawn for but one phase of the motor. The values of power, losses, and torque must be multiplied by n if the motor has n phases. The torque scale may be found as follows: The torque is equal to a constant times the power, divided by the speed, the value of the constant depending on the units adopted. The power output per phase is $P = V X DE$. The rotor speed $N_2 = N (1 - s)$ where N is the synchronous speed in r. p. m. $CD = N(CE - CD) = N^2 CE CE CE$. The torque developed per phase K is $CE V X C$ z s the total power per phase delivered to the rotor. The total power delivered to the rotor by n phases, $P_2 = n \dots$



[Read A course in electrical engineering Volume 2 Online](#)



[Download PDF A course in electrical engineering Volume 2](#)

See Also



[PDF] The Whale Tells His Side of the Story Hey God, Ive Got Some Guy Named Jonah in My Stomach and I Think Im Gonna Throw Up

Click the hyperlink beneath to download and read "The Whale Tells His Side of the Story Hey God, Ive Got Some Guy Named Jonah in My Stomach and I Think Im Gonna Throw Up" PDF file.

[Read Document »](#)



[PDF] God Loves You. Chester Blue

Click the hyperlink beneath to download and read "God Loves You. Chester Blue" PDF file.

[Read Document »](#)



[PDF] Animalogy: Animal Analogies

Click the hyperlink beneath to download and read "Animalogy: Animal Analogies" PDF file.

[Read Document »](#)



[PDF] Yearbook Volume 15

Click the hyperlink beneath to download and read "Yearbook Volume 15" PDF file.

[Read Document »](#)



[PDF] Molly on the Shore, BFMS 1 Study score

Click the hyperlink beneath to download and read "Molly on the Shore, BFMS 1 Study score" PDF file.

[Read Document »](#)



[PDF] Good Night, Zombie Scary Tales

Click the hyperlink beneath to download and read "Good Night, Zombie Scary Tales" PDF file.

[Read Document »](#)